O₂ Gas Sensor to Spirometer Adapter

(Order Code O2-SPR)



The O_2 Gas Sensor to Spirometer Adapter allows the user to connect an Oxygen Gas Sensor to a Spirometer. Respiratory volumes and oxygen concentrations of inhaled and exhaled air can then be recorded simultaneously. The bacterial filter that comes with the Spirometer is attached to the inlet of the adapter to keep the system sterile.



NOTE: This product is to be used for educational purposes only. It is not appropriate for industrial, medical, research, or commercial applications.

Important Additional Information

• Do not autoclave. Wash the adapter using mild liquid dishwashing detergent. Rinse with tap or distilled water and allow to air dry.



Measure. Analyze. Learn. Vernier Software & Technology

13979 S.W. Millikan Way • Beaverton, OR 97005-2886
Toll Free (888) 837-6437 • (503) 277-2299 • FAX (503) 277-2440
info@vernier.com • www.vernier.com

Rev. 8/8/1

All marks not owned by us that appear herein are the property of their respective owners, who may or may not be affiliated with, connected to, or sponsored by us.



Printed on recycled paper